


## 1 Software Installation:



1.1 Put the software CD into the drive to read the files

1.2 Click the application software in the CH341SerSetup folder  Install USB to serial port driver


1.3 Click the T5LTest (Setup) document, and then click the application

 software installation


## 2 Data Download:

Click on  Pop-up window appears  Click OK to download the data and wait for the data download to complete, (save)(cancel) ,Click to save the record file

## 3 Export Excel file:

Click on  Choose export, appear(save)(cancel),Click save to export the file to "XLS" format

## 4 Correct the clock:

Click on  Select the clock to be calibrated, a pop-up window appears and click OK